









Wiring instruction for coax S6 75 ohms

PICTURE	PROCESS	CHECK	TOOLS
	<p>STRIP THE JACKET</p>	<p>DO NOT DAMAGE THE BRAID</p>	<p>BLADE</p>
	<p>CUT THE BRAID AS SHOWN</p>	<p>DO NOT DAMAGE THE INNER CONDUCTOR</p>	<p>BLADE</p>
	<p>STRIP INNER CONTACT SLIDE THE CRIMPING FERULE OVER THE CABLE</p>		
	<p>INSERT THE INNER CONTACT ON THE INNER WIRE CRIMP INNER PIN CONTACT</p>	<p>THE INNER CONDUCTOR SHALL BE VISIBLE THRU THE INSPECTION HOLE</p>	<p>M22520/2-01 WITH POSITIONNER K709 (1)</p>
	<p>SLIDE THE OUTER CRIMPING BODY AND IT NUT UNDERNEATH THE BRAID AND THE CABLE INSULATOR</p>		
	<p>CLIP THE REAR INSERT ON THE INNER CONTACT BEHIND THE CONTACT FLANGE</p>		
	<p>INSERT THE FRONT INSERT OVER THE INNER CONTACT</p>		
	<p>PUSH THE SUB-ASSEMBLY UNTIL MECHANICAL STOP THEN SCREW THE NUT. THE COUPLING TORQUE SHALL NOT EXCEED 0,25N.m STITCH DOWN THE BRAID OVER THE CRIMPING BODY THEN SLIDE THE CRIMPING FERULE CRIMP THE FERULE</p>	<p>TAKE OFF THE BRAID AFTER CRIMPING</p>	<p>M22520/5-01 WITH DIES M22520/5-08 (A)</p>