


# **TECHNICAL NOTE** CRIMP MHDAS : INSTRUCTIONS



**EXTERNAL DIFFUSION** 

Technical note n°: BLP-ER-015-Ext

Revision C, July 2023

- Prepared by: Matthieu GERVAIS Business Division Avionics R&D Engineer / Amphenol Socapex
- Approved by: Thomas CARLIER Business Division Avionics Product Manager / Amphenol Socapex

ISSUED BY: Amphenol Socapex 948, Promenade de l'Arve – B.P. 29 74311 Thyez Cedex - France Tél. : +33 (0) 4 50 89 28 00 www.amphenol-socapex.com

The information contained in this document is proprietary to Amphenol Socapex France and is made available in confidence. It must not be used or disclosed without the express written permission of Amphenol Socapex France. This document may not be copied in whole or in part in any form without the express written consent of Amphenol Socapex France.

# Amphenol SOCAPEX


## 1. CRIMPING INSTRUCTION

#### 1.1.TOOLS


✓ Set the hand crimp tool, the positioner, and the selector number according to wire and crimp barrel size:

WIRE SIZE	CONTACT		HAND CRIMP TOOL	POSITIONER	SELECTOR NUMBER
AWG	TYPE	GENDER			NUIVIDER
24	А	Male	MH800	K1692	4
		Female			
26	В	Male			
		Female			
28	G	Male			
30		Female			

- **1.2. WIRE STRIPPING**
- ✓ Check the wire stripping:



The conductor must be visible through the inspection hole of the contact:





#### 1.3. CRIMPING

- ✓ Insert the contact and wire assembly in the positioner mounted in the hand crimp tool.
- ✓ Ensure that the contact is well positioned in the positioner, keep the wire in position.
- ✓ Crimp the contact and wire assembly 1 crimping operation is enough.

#### 1.4. CHECK

- <u>Visual</u>: The conductor is visible in the inspection hole, crimping is centered between the inspection hole and the barrel entrance, the contact must not have any cracks, plating detachment
- ✓ <u>Retention:</u> pinch the cable and pull it gently


#### 2. CRIMP CONTACT INSERTION INSTRUCTION

#### 2.1. TOOL & PREPARATION


✓ Use specific MHDAS crimp contact insertion tool **MHDASODIEC**:



✓ Place the insulator on a flat surface, pressing on both extremities:




 ✓ Place the wire into the insertion tip, push the contact barrel against the tool (1) and grip the tool with your fingers (2):



# Amphenol SOCAPEX

#### 2.2. INSERTION

- ✓ Keep the tool closed (1)
- ✓ Push on the tool to insert the contact into the insulator cavity (2), make sure you stay in the axis of the contact and the cavity.
  - ► Push the contact to the bottom of the cavity



### 2.3. CHECK

- ✓ <u>Visual:</u> Contact must have clearance with the housing, contact can rotate freely inside the housing
- ✓ <u>Retention</u>: pinch the cable and pull it gently

## 3. BACKPOTTING INFORMATION

We recommend the use of *Skycast 2651MM and Catalyst 9 (10%)* for enhanced protection.