



Avis de Modification Produit / Process <i>Product / Process Change</i> <i>Notification</i>		Référence / Reference PCN 115542	
		Page / Page 1/1	Date de Diffusion / <i>Issue Date</i> 07/05/2013
Familles Produit / <i>Product Families</i>	SIAL	Articles / Part <i>Numbers</i>	Tout ASLE, ASLP, et ASLT
Origine / Origine	Amphenol Socapex France	Diffusion / <i>Distribution</i>	Tous clients / <i>All customers</i>

Sujet / Subject

Suite à des coûts de non qualité récurrents, Amphenol Socapex a décidé de revoir le design de la face avant des contacts femelles de la série SIAL. Les lyres peuvent présenter une ouverture insuffisante dans certains cas de figure, et rentrer en conflit avec la contre-partie mâle. On se propose ici d'augmenter la largeur d'ouverture de 0,1mm.

Further to recurring non-quality costs on our SIAL series, Amphenol Socapex decided to upgrade the mating end of the female sockets. In some cases, the opening of the tuning fork may not be sufficient, and could interfere with the male counterpart. Therefore this opening gap has been increased of 0,1mm.

Modification / Nature of Change

 Changement de design / *Design upgrade*
Date d'application / Implementation Date

 1^{er} Octobre 2013 approx. / *October, 2013, 1st. approx..*
APPROBATIONS / Approvals

Engineering	Matthieu TAGAND - 07/05/2013	Marketing	Olivier GAVARD - 07/05/2013
Quality	Christel JULLIAN - 07/05/2013	Industrial	Christel JULLIAN - 07/05/2013